SECRET

12 NOV 1963

1963 NOV 9

HFS CJS CFC. ZPNŠ

OUT-52265 FM CIA WASHDC RUCSBR/SAC OFFUTT AFB, OMAHA, NEB RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA RUEAHQ/DIAXX RUECYG/NAVY PIC RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF RUWGAA/2D RTS, BARKSDALE AFB, LA RUNGAA/2AF, BÄRKSDALE AFB, LÄ

40

ACL

19

CITE CIA-Z+1007 SECRET

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM4) 2D AF FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

- CAMERA B 8 WAS USED IN MISSION 3768 FLOWN 6 NOV 63; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.
  - ORIGINAL NEGATIVE

DA GRNC

BT

- THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS FAIR DUE TO THE GRAINY APPEARANCE OF THE IMAGERY.
- OR SIDE: A HEAT SPLICE IS PRESENT THROUGH FRAMES 586 AND 1285. A FEW SCATTERED PINHOLES ARE NOTED THROUGHOUT THIS MISSION.
- 9L SIDE: A HEAT SPLICE IS PRESENT THROUGH FRAMES 597 ASSOCIATED WITH THE LATTER SPLICE ARE CRIMPS AND AND 1307. SKIVING ADHERING TO THE EMULSION DIGS ON FRAMES 1307 AND 1308. TRAILING EDGE OF THE FRAME FORMAT RESULTS IN A MINOR OBSTRUCTION ON EVERY FRAME THROUGHOUT THE MISSION. A MINUS DENSITY DOTS

Declassification Review by NGA/DoD



OCCURS 3.12" FROM THE OUTBOARD EDGE OF THE FILM ON FRAME 1888.
A FEW SCATTERED PINHOLES AND BLISTERS OCCUR THROUGHOUT THIS SIDE.

- D. BOTH SIDES: THE METERING IS ERRATIC WITH NO OVERLAPPING FORMATS NOTED. THE DATA CHAMBER CLOCK IS READABLE BUT SLIGHTLY OVEREXPOSED. THE INDICATOR LAMPS FLUCTUATED IN INTENSITY THROUGHOUT THIS MISSION, WITH THE 1L POSITION LAMP OPERATING INTERMITTENTLY. A REFLECTION FROM THE FRAME FORMAT APPEARS THROUGHOUT, WITH OCCASIONAL, RAIL FLARE ON THE LEADING AND OUTBOARD EDGE POSSIBLY DUE TO VEHICLE MANEUVERING.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THIS MISSION.
  - 3. POSITIVE
- A. PI SUITABILITY IS FAIR DUE TO THE GRAINY APPEARANCE OF THE IMAGERY.
  - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 20 PERCENT OF THE MISSION.
  SECRET

END OF MESSAGE